

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
64242	Base unit	Basement	1	ok	0.12	>50	ok			Pass	
64243	IEC lead	Basement	1	ok	0.09	>50	ok		5	Pass	
64244	Monitor	Basement	1	ok	0.15	>50	ok			Pass	
64245	IEC lead	Basement	1	ok	0.06	>50	ok		13	Pass	
64246	4 way extension	Basement	1	ok	0.13	>50	ok		13	Pass	
64247	Convactor heater	Basement	1	ok	0.07	>50	ok		13	Pass	
64248	AC adaptor	Basement	1	ok		>50	ok			Pass	
64249	IEC lead	Basement	1	ok	0.05	>50	ok		5	Pass	
64250	Base unit	Basement	1	ok	0.08	>50	ok			Pass	
64251	IEC lead	Basement	1	ok	0.06	>50	ok		5	Pass	
64252	Base unit	Basement	1	ok	0.10	>50	ok			Pass	
64253	IEC lead	Basement	1	ok	0.09	>50	ok		13	Pass	
64254	Monitor	Basement	1	ok	0.15	>50	ok			Pass	
64255	IEC lead	Basement	1	ok	0.12	>50	ok		13	Pass	
64256	4 way extension	Basement	1	ok	0.07	>50	ok		13	Pass	
64257	Photocopier	Basement	1	ok	0.17	>50	ok			Pass	
64258	IEC lead	Basement	1	ok	0.08	>50	ok		13	Pass	
64259	Monitor	Basement	1	ok	0.08	>50	ok			Pass	
64260	IEC lead	Basement	1	ok	0.06	>50	ok		13	Pass	
64261	4 way extension	Basement	1	ok	0.05	>50	ok		13	Pass	
64262	IEC lead	Basement	1	ok	0.05	>50	ok		13	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
64263	IEC lead	Basement	1	ok	0.05	>50	ok		10	Pass	
64264	Power lead	Basement	2	ok		>50	ok		3	Pass	
64265	4 way extension	Basement	1	ok	0.03	>50	ok		13	Pass	
64266	IEC lead	Basement	1	ok	0.05	>50	ok		5	Pass	
64267	Fan heater	Basement	2	ok		>50	ok		13	Pass	
64268	Fan heater	Basement	2	ok		>50	ok		13	Pass	
64269	4 way extension	Basement	1	ok	0.10	>50	ok		13	Pass	
64270	4 way extension	Basement	1	ok	0.08	>50	ok		13	Pass	
64271	IEC lead	Basement	1	ok	0.04	>50	ok			Pass	
64272	IEC lead	Basement	1	ok	0.05	>50	ok		5	Pass	
64273	Base unit	Basement	1	ok	0.11	>50	ok			Pass	
64274	IEC lead	Basement	1	ok	0.07	>50	ok		10	Pass	
64275	IEC lead	Basement	1	ok	0.05	>50	ok		5	Pass	
64276	Monitor	Basement	1	ok	0.08	>50	ok			Pass	
64277	IEC lead	Basement	1	ok	0.07	>50	ok		5	Pass	
64278	Monitor	Basement	1	ok	0.01	>50	ok			Pass	
64279	IEC lead	Basement	1	ok	0.12	>50	ok		5	Pass	
64280	6 way extension	Basement	1	ok	ok		ok			Pass	
64281	4 way extension	Basement	1	ok	ok		ok			Pass	
64282	4 way extension	Basement	1	ok	ok		ok			Pass	
64283	10 way extension	Basement	1	ok	ok		ok			Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
64284	Transformer	Basement	1	ok		>50	ok		5	Pass	
64285	Base unit	Basement	1	ok	0.13	>50	ok			Pass	
64286	IEC lead	Basement	1	ok	0.09	>50	ok		5	Pass	
64287	Monitor	Basement	1	ok	0.14	>50	ok			Pass	
64288	IEC lead	Basement	1	ok	0.08	>50	ok		5	Pass	
64289	3 way adaptor	Basement	1	ok	0.02	>50	ok		13	Pass	
64290	Monitor	Basement	1	ok	0.18	>50	ok			Pass	
64291	IEC lead	Basement	1	ok	0.10	>50	ok		10	Pass	
64292	Monitor	Basement	1	ok	0.10	>50	ok			Pass	
64293	IEC lead	Basement	1	ok	0.08	>50	ok		5	Pass	
64294	Photocopier	Basement	1	ok	0.08	>50	ok			Pass	
64295	IEC lead	Basement	1	ok	0.09	>50	ok		13	Pass	
64296	Franking machine	Basement	1	ok	0.08	>50	ok			Pass	
64297	IEC lead	Basement	1	ok	0.05	>50	ok		5	Pass	
64298	Base unit	Basement	1	ok	0.11	>50	ok			Pass	
64299	IEC lead	Basement	1	ok	0.09	>50	ok		10	Pass	
64300	4 way extension	Basement	1	ok	0.07	>50	ok		13	Pass	
64301	Kettle	Basement	1	ok	0.07	>50	ok		13	Pass	
64302	Kettle	Basement	1	ok	0.12	>50	ok		13	Pass	
64303	Toaster	Basement	1	ok	0.08	>50	ok		13	Pass	
64304	Microwave	Basement	1	ok	0.12	>50	ok		13	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
64305	Fridge	Basement	1	ok	0.06	>50	ok		13	Pass	Reterminated
64306	Dishwasher	Basement	1	ok	0.11	>50	ok		13	Pass	
64307	Fridge	Ground floor	1	ok		>50	ok		13	Pass	
64308	2 way extension	Ground floor	1	ok	0.06	>50	ok		13	Pass	
64309	Printer	Ground floor	1	ok	0.10	>50	ok			Pass	
64310	IEC lead	Ground floor	1	ok	0.09	>50	ok		13	Pass	
64311	Fan	Ground floor	2	ok		>50	ok		3	Pass	
64312	Lamp	Ground floor	2	ok		>50	ok		3	Pass	
64313	Base unit	Ground floor	1	ok	0.09	>50	ok			Pass	
64314	IEC lead	Ground floor	1	ok	0.08	>50	ok		10	Pass	
64315	Lamp	Ground floor	2	ok		>50	ok		3	Pass	
64316	Monitor	Ground floor	1	ok	0.15	>50	ok			Pass	
64317	IEC lead	Ground floor	1	ok	0.11	>50	ok		5	Pass	
64318	IEC lead	Ground floor	1	ok	0.08	>50	ok		5	Pass	
64319	Convactor heater	Ground floor	1	ok	0.05	>50	ok		13	Pass	
64320	Power lead	Ground floor	2	ok		>50	ok		3	Pass	
64321	4 way extension	Ground floor	1	ok	0.06	>50	ok		13	Pass	
64322	Printer	Ground floor	1	ok	0.12	>50	ok			Pass	
64323	IEC lead	Ground floor	1	ok	0.08	>50	ok		5	Pass	
64324	Base unit	Ground floor	1	ok	0.13	>50	ok			Pass	
64325	IEC lead	Ground floor	1	ok	0.11	>50	ok		10	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
64326	Monitor	Ground floor	1	ok	0.19	>50	ok			Pass	
64327	IEC lead	Ground floor	1	ok	0.08	>50	ok		10	Pass	
64328	4 way extension	Ground floor	1	ok	0.12	>50	ok		13	Pass	Fuse replaced
64329	Water cooler	Ground floor	1	ok	0.12	>50	ok		5	Pass	
65007	4 way extension	2nd floor	1	ok	0.19	>50	ok		13	Pass	Reterminated
65008	Monitor	2nd floor	1	ok	0.18	>50	ok			Pass	
65009	IEC lead	2nd floor	1	ok	0.08	>50	ok			Pass	
65010	IEC lead	2nd floor	1	ok	0.04	>50	ok		10	Pass	
65011	Base unit	2nd floor	1	ok	0.15	>50	ok			Pass	
65012	IEC lead	2nd floor	1	ok	0.05	>50	ok			Pass	
65013	IEC lead	2nd floor	1	ok	0.04	>50	ok		10	Pass	
65014	IEC lead	2nd floor	1	ok	0.05	>50	ok		10	Pass	
65015	Appliance	2nd floor	1	ok	0.04	>50	ok			Pass	
65016	Transformer	2nd floor	2	ok		>50	ok		3	Pass	
65017	4 way extension	2nd floor	1	ok	0.07	>50	ok		13	Pass	
65018	Transformer	2nd floor	2	ok		>50	ok		3	Pass	
65019	IEC lead	2nd floor	1	ok	0.07	>50	ok		5	Pass	
65020	IEC lead	2nd floor	1	ok	0.06	>50	ok		10	Pass	
65021	Transformer	2nd floor	1	ok	0.14	>50	ok		13	Pass	
65022	IEC lead	2nd floor	1	ok	0.05	>50	ok		5	Pass	
65023	Base unit	2nd floor	1	ok	0.10	>50	ok			Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65024	IEC lead	2nd floor	1	ok	0.05	>50	ok		5	Pass	
65025	Printer	2nd floor	1	ok	0.09	>50	ok			Pass	
65026	4 way extension	2nd floor	1	ok	0.09	>50	ok		13	Pass	
65027	Fan	2nd floor	1	ok	0.10	>50	ok		3	Pass	
65028	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65029	IEC lead	2nd floor	1	ok	0.05	>50	ok		13	Pass	
65030	Printer	2nd floor	1	ok	0.03	>50	ok			Pass	
65031	Fan	2nd floor	1	ok	0.06	>50	ok		3	Pass	
65032	Fan	2nd floor	1	ok	0.10	>50	ok		3	Pass	
65033	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65034	IEC lead	2nd floor	1	ok	0.19	>50	ok		5	Pass	
65035	4 way extension	2nd floor	1	ok	0.07	>50	ok		13	Pass	
65036	IEC lead	2nd floor	1	ok	0.10	>50	ok		13	Pass	
65037	IEC lead	2nd floor	1	ok	0.06	>50	ok		10	Pass	
65038	Printer	2nd floor	1	ok	0.06	>50	ok			Pass	
65039	IEC lead	2nd floor	1	ok	0.08	>50	ok		5	Pass	
65040	Base unit	2nd floor	1	ok	0.16	>50	ok			Pass	
65041	IEC lead	2nd floor	1	ok		>50	ok		10	Pass	
65042	Tuner	2nd floor	1	ok	0.08	>50	ok			Pass	
65043	Fan	2nd floor	1	FAIL						FAIL	Cover damaged
65044	Fan	2nd floor	1	ok	0.18	>50	ok		3	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65045	Printer	2nd floor	1	ok	0.04	>50	ok			Pass	
65046	IEC lead	2nd floor	1	ok	0.10	>50	ok		10	Pass	
65047	IEC lead	2nd floor	1	ok	0.06	>50	ok		5	Pass	
65048	IEC lead	2nd floor	1	ok	0.11	>50	ok		13	Pass	
65049	Printer	2nd floor	1	ok	0.08	>50	ok			Pass	
65050	Printer	2nd floor	1	ok	0.08	>50	ok			Pass	
65051	IEC lead	2nd floor	1	ok	0.05	>50	ok		10	Pass	
65053	4 way extension	2nd floor	1	ok	0.17	>50	ok		13	Pass	
65054	IEC lead	2nd floor	1	ok	0.10	>50	ok		5	Pass	
65055	IEC lead	2nd floor	1	ok	0.08	>50	ok		13	Pass	
65057	Base unit	2nd floor	1	ok	0.06	>50	ok			Pass	
65056	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65058	Fan	2nd floor	1	ok	0.15	>50	ok		3	Pass	
65059	Lamp	2nd floor	1	ok	0.18	>50	ok		3	Pass	
65060	IEC lead	2nd floor	1	ok	0.07	>50	ok		5	Pass	
65061	IEC lead	2nd floor	1	ok	0.05	>50	ok		13	Pass	
65062	IEC lead	2nd floor	1	ok	0.07	>50	ok		5	Pass	
65063	4 way extension	2nd floor	1	ok	0.10	>50	ok		13	Pass	
65064	Printer	2nd floor	1	ok	0.05	>50	ok			Pass	
65065	Base unit	2nd floor	1	ok	0.07	>50	ok			Pass	
65066	Monitor	2nd floor	1	ok	0.12	>50	ok			Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65067	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65068	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65069	4 way extension	2nd floor	1	ok	0.09	>50	ok		13	Pass	
65070	Transformer	2nd floor	1	ok	0.08	>50	ok		13	Pass	
65071	IEC lead	2nd floor	1	ok	0.05	>50	ok		13	Pass	
65072	IEC lead	2nd floor	1	ok	0.06	>50	ok		13	Pass	
65073	Printer	2nd floor	1	ok	0.07	>50	ok			Pass	
65074	Base unit	2nd floor	1	ok	0.11	>50	ok			Pass	
65075	Fridge	2nd floor	1	ok	0.07	>50	ok		5	Pass	
65076	Water heater	2nd floor	1	ok	0.14	>50	ok		13	Pass	
65077	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65078	Base unit	2nd floor	1	ok	0.13	>50	ok			Pass	
65079	Water cooler	2nd floor	1	ok	0.19	>50	ok		5	Pass	
65080	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65081	4 way extension	2nd floor	1	ok	0.05	>50	ok		13	Pass	
65082	IEC lead	2nd floor	1	ok	0.06	>50	ok		10	Pass	
65083	IEC lead	2nd floor	1	ok	0.07	>50	ok		13	Pass	
65084	IEC lead	2nd floor	1	ok	0.02	>50	ok		5	Pass	
65085	AC adaptor	2nd floor	1	ok	0.17	>50	ok		13	Pass	
65086	Printer	2nd floor	1	ok	0.07	>50	ok			Pass	
65087	Monitor	2nd floor	1	ok	0.12	>50	ok			Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65088	Base unit	2nd floor	1	ok	0.07	>50	ok			Pass	
65089	4 way extension	2nd floor	1	ok	0.12	>50	ok		13	Pass	
65090	IEC lead	2nd floor	1	ok	0.06	>50	ok		5	Pass	
65091	IEC lead	2nd floor	1	ok	0.07	>50	ok		5	Pass	
65092	Transformer	2nd floor	2	ok		>50	ok			Pass	
65093	Monitor	2nd floor	1	ok	0.07	>50	ok			Pass	
65094	Base unit	2nd floor	1	ok	0.09	>50	ok			Pass	
65095	4 way extension	2nd floor	1	ok	0.08	>50	ok		13	Pass	
65096	IEC lead	2nd floor	1	ok	0.02	>50	ok		10	Pass	
65097	IEC lead	2nd floor	1	ok	0.08	>50	ok		10	Pass	
65098	Transformer	2nd floor	1	ok	0.13	>50	ok		13	Pass	
65099	Monitor	2nd floor	1	ok	0.07	>50	ok			Pass	
65100	Base unit	2nd floor	1	ok	0.12	>50	ok			Pass	
65101	IEC lead	2nd floor	1	ok	0.02	>50	ok		10	Pass	
65102	Printer	2nd floor	1	ok	0.05	>50	ok			Pass	
65103	IEC lead	2nd floor	1	ok	0.13	>50	ok		13	Pass	
65104	IEC lead	2nd floor	1	ok	0.08	>50	ok		5	Pass	
65105	Fan	2nd floor	1	ok	0.18	>50	ok		3	Pass	
65106	4 way extension	2nd floor	1	ok	0.10	>50	ok		13	Pass	
65107	Printer	2nd floor	2	ok		>50	ok		3	Pass	
65108	Lamp	2nd floor	1	ok	0.13	>50	ok		3	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65109	IEC lead	2nd floor	1	ok	0.12	>50	ok		13	Pass	
65110	IEC lead	2nd floor	1	ok	0.05	>50	ok		13	Pass	
65119	Base unit	2nd floor	1	ok	0.12	>50	ok			Pass	
65111	4 way extension	2nd floor	1	ok	0.12	>50	ok		13	Pass	
65112	IEC lead	2nd floor	1	ok	0.07	>50	ok		10	Pass	
65113	IEC lead	2nd floor	1	ok	0.11	>50	ok		10	Pass	
65114	Monitor	2nd floor	1	ok	0.04	>50	ok			Pass	
65115	Base unit	2nd floor	1	ok	0.07	>50	ok			Pass	
65116	IEC lead	2nd floor	1	ok	0.13	>50	ok		10	Pass	
65117	IEC lead	2nd floor	1	ok	0.08	>50	ok		13	Pass	
65118	Monitor	2nd floor	1	ok	0.12	>50	ok			Pass	
65119	Base unit	2nd floor	1	ok	0.06	>50	ok			Pass	
65121	Heater	2nd floor	2	ok		>50	ok		13	Pass	
65122	Lamp	2nd floor	2	ok		>50	ok		3	Pass	
65123	Transformer	2nd floor	2	ok		>50	ok		5	Pass	
65124	4 way extension	2nd floor	1	ok	0.08	>50	ok		13	Pass	
65125	IEC lead	2nd floor	1	ok	0.16	>50	ok		5	Pass	
65126	IEC lead	2nd floor	1	ok	0.08	>50	ok		10	Pass	
65127	4 way extension	2nd floor	1	ok	0.14	>50	ok		13	Pass	
65128	Printer	2nd floor	1	ok	0.18	>50	ok			Pass	
65129	IEC lead	2nd floor	1	ok	0.06	>50	ok			Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65130	IEC lead	2nd floor	1	ok	0.09	>50	ok		13	Pass	
65131	Monitor	2nd floor	1	ok	0.07	>50	ok			Pass	
65132	Base unit	2nd floor	1	ok	0.07	>50	ok			Pass	
65133	4 way extension	2nd floor	1	ok	0.16	>50	ok		13	Pass	
65134	4 way extension	2nd floor	1	ok	0.09	>50	ok		13	Pass	
65135	IEC lead	2nd floor	1	ok	0.05	>50	ok		5	Pass	
65136	IEC lead	2nd floor	1	ok	0.03	>50	ok		5	Pass	
65137	IEC lead	2nd floor	1	ok	0.07	>50	ok		10	Pass	
65138	Monitor	2nd floor	1	ok	0.08	>50	ok			Pass	
65139	Base unit	2nd floor	1	ok	0.05	>50	ok			Pass	
65140	Printer	2nd floor	1	ok	0.11	>50	ok			Pass	
65141	IEC lead	2nd floor	1	ok	0.12	>50	ok		10	Pass	
65142	IEC lead	2nd floor	1	ok	0.07	>50	ok		10	Pass	
65143	IEC lead	2nd floor	1	ok	0.05	>50	ok		5	Pass	
65144	4 way extension	2nd floor	1	ok	0.18	>50	ok		13	Pass	
65145	Lamp	2nd floor	2	ok		>50	ok		3	Pass	
65146	Printer	2nd floor	1	ok	0.14	>50	ok			Pass	
65147	Base unit	2nd floor	1	ok	0.07	>50	ok			Pass	
65148	Heater	2nd floor	2	ok		>50	ok		3	Pass	
65149	Lamp	2nd floor	1	ok	0.11	>50	ok		3	Pass	
65150	Lamp	2nd floor	1	ok	0.04	>50	ok		3	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65151	IEC lead	2nd floor	1	ok		>50	ok		5	Pass	
65152	IEC lead	2nd floor	1	ok		>50	ok		5	Pass	
65153	IEC lead	2nd floor	1	ok		>50	ok		13	Pass	
65154	Printer	2nd floor	1	ok	0.05	>50	ok			Pass	
65155	Monitor	2nd floor	1	ok	0.07	>50	ok			Pass	
65156	Base unit	2nd floor	1	ok	0.04	>50	ok			Pass	
65161	Fan	2nd floor	1	ok		>50	ok		3	Pass	
65162	Heater	2nd floor	1	ok	0.10	>50	ok		13	Pass	
65163	Base unit	2nd floor	1	ok	0.07	>50	ok			Pass	
65164	IEC lead	2nd floor	1	ok	0.06	>50	ok		5	Pass	
65165	Monitor	2nd floor	1	ok	0.14	>50	ok			Pass	
65166	IEC lead	2nd floor	1	ok	0.08	>50	ok		5	Pass	
65167	4 way extension	2nd floor	1	ok	0.07	>50	ok		13	Pass	
65168	AC adaptor	2nd floor	2	ok		>50	ok		5	Pass	
65169	Lamp	2nd floor	1	ok	0.16	>50	ok		5	Pass	
65170	Base unit	2nd floor	1	ok	0.06	>50	ok			Pass	
65171	IEC lead	2nd floor	1	ok	0.07	>50	ok		13	Pass	
65172	Monitor	2nd floor	1	ok	0.12	>50	ok			Pass	
65173	IEC lead	2nd floor	1	ok	0.05	>50	ok		10	Pass	
65174	4 way extension	2nd floor	1	ok	0.05	>50	ok		13	Pass	
65175	4 way extension	2nd floor	1	ok	0.08	>50	ok		13	Pass	Reterminated

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65176	Power lead	2nd floor	2	ok		>50	ok		3	Pass	Fuse replaced
65177	Power lead	2nd floor	2	ok		>50	ok		3	Pass	
65178	Power lead	2nd floor	2	ok		>50	ok		3	Pass	
65179	Photocopier	2nd floor	1	ok	0.09	>50	ok			Pass	
65180	IEC lead	2nd floor	1	ok	0.07	>50	ok		13	Pass	
65181	IEC lead	2nd floor	1	ok	0.09	>50	ok		5	Pass	
65182	Heater	1st floor	1	ok	0.06	>50	ok		13	Pass	
65183	Base unit	1st floor	1	ok	0.16	>50	ok			Pass	
65184	IEC lead	1st floor	1	ok	0.07	>50	ok		5	Pass	
65185	Monitor	1st floor	1	ok	0.14	>50	ok			Pass	
65186	IEC lead	1st floor	1	ok	0.04	>50	ok		13	Pass	
65187	2 way adaptor	1st floor	1	ok	0.02	>50	ok		13	Pass	
65188	Printer	1st floor	1	ok	0.14	>50	ok			Pass	
65189	IEC lead	1st floor	1	ok	0.06	>50	ok		10	Pass	
65190	Printer	1st floor	1	ok	0.07	>50	ok			Pass	
65191	IEC lead	1st floor	1	ok	0.06	>50	ok		10	Pass	
65192	Base unit	1st floor	1	ok	0.14	>50	ok			Pass	
65193	IEC lead	1st floor	1	ok	0.03	>50	ok		5	Pass	
65194	Monitor	1st floor	1	ok	0.14	>50	ok			Pass	
65195	IEC lead	1st floor	1	ok	0.05	>50	ok		13	Pass	
65196	4 way extension	1st floor	1	ok	0.05	>50	ok		13	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65197	Power lead	1st floor	2	ok		>50	ok		3	Pass	Fuse replaced
65198	Fan	1st floor	1	ok		>50	ok		3	Pass	
65199	4 way extension	1st floor	1	ok	0.09	>50	ok		13	Pass	
65200	IEC lead	1st floor	1	ok	0.05	>50	ok		5	Pass	
65201	IEC lead	1st floor	1	ok	0.04	>50	ok		10	Pass	
65202	AC adaptor	1st floor	1	ok		>50	ok			Pass	
65203	Base unit	1st floor	1	ok	0.13	>50	ok			Pass	
65204	IEC lead	1st floor	1	ok	0.05	>50	ok		13	Pass	
65205	Printer	1st floor	1	ok	0.09	>50	ok			Pass	
65206	IEC lead	1st floor	1	ok	0.04	>50	ok		13	Pass	
65207	4 way extension	1st floor	1	ok	0.09	>50	ok		13	Pass	
65208	IEC lead	1st floor	1	ok	0.10	>50	ok		13	Pass	
65209	Printer	1st floor	1	ok	0.11	>50	ok			Pass	
65210	Base unit	1st floor	1	ok	0.06	>50	ok			Pass	
65211	Base unit	1st floor	1	ok	0.12	>50	ok			Pass	
65212	IEC lead	1st floor	1	ok	0.05	>50	ok		5	Pass	
65213	Monitor	1st floor	1	ok	0.14	>50	ok			Pass	
65214	IEC lead	1st floor	1	ok	0.05	>50	ok		13	Pass	
65215	Fan	1st floor	1	ok		>50	ok		3	Pass	
65216	Heater	1st floor	1	ok	0.10	>50	ok		13	Pass	
65217	IEC lead	1st floor	1	ok	0.13	>50	ok		5	Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65218	IEC lead	1st floor	1	ok	0.06	>50	ok		13	Pass	
65219	Base unit	1st floor	1	ok	0.12	>50	ok			Pass	
65220	IEC lead	1st floor	1	ok	0.05	>50	ok		5	Pass	
65221	Monitor	1st floor	1	ok	0.11	>50	ok			Pass	
65222	IEC lead	1st floor	1	ok	0.07	>50	ok		13	Pass	
65223	4 way extension	1st floor	1	ok	0.12	>50	ok		13	Pass	
65224	Printer	1st floor	1	ok	0.15	>50	ok			Pass	
65225	IEC lead	1st floor	1	ok	0.05	>50	ok			Pass	
65226	4 way extension	1st floor	1	ok	0.13	>50	ok		13	Pass	
65227	IEC lead	1st floor	1	ok	0.07	>50	ok		10	Pass	
65228	Photocopier	1st floor	1	ok	0.15	>50	ok			Pass	
65229	IEC lead	1st floor	1	ok	0.05	>50	ok		13	Pass	
65230	IEC lead	Ground floor	1	ok	0.06	>50	ok		5	Pass	
65231	IEC lead	Ground floor	1	ok	0.07	>50	ok		13	Pass	
65232	Heater	Ground floor	1	ok	0.10	>50	ok		13	Pass	
65233	Fan	Ground floor	1	ok		>50	ok		5	Pass	
65234	Lamp	Ground floor	1	ok	0.14	>50	ok		3	Pass	
65241	Lamp	Ground floor	1	ok	0.08	>50	ok		3	Pass	Reterminated
65235	Base unit	Ground floor	1	ok	0.12	>50	ok			Pass	
65236	IEC lead	Ground floor	1	ok	0.05	>50	ok		10	Pass	
65237	Printer	Ground floor	1	ok	0.07	>50	ok			Pass	

Portable Appliance Test Results											
Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician:		Ian Clifford			
Date: 14th May 2013						Tester:		Primetest 200 X11-1203			
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation (MΩ)	Polarity	M/W Emmission mW/cm2	Fuse	Pass / Fail	Comments
65238	IEC lead	Ground floor	1	ok	0.05	>50	ok		13	Pass	
65239	AC adaptor	Ground floor	1	ok	0.07	>50	ok		13	Pass	
65240	Lamp	Ground floor	2	ok		>50	ok		3	Pass	
65242	4 way extension	Ground floor	1	ok	0.13	>50	ok		13	Pass	
65243	4 way extension	Ground floor	1	ok	0.12	>50	ok		13	Pass	
65244	Lamp	Ground floor	1	ok	0.11	>50	ok		3	Pass	
65245	1 way extension	Ground floor	1	ok	0.17	>50	ok		13	Pass	
65246	Lamp	Ground floor	1	ok	0.12	>50	ok		3	Pass	
65247	Heater	Ground floor	1	ok	0.16	>50	ok		13	Pass	
65248	Base unit	Ground floor	1	ok	0.14	>50	ok			Pass	
65249	IEC lead	Ground floor	1	ok	0.05	>50	ok		5	Pass	
65250	Monitor	Ground floor	1	ok	0.12	>50	ok			Pass	
65251	IEC lead	Ground floor	1	ok	0.07	>50	ok		5	Pass	
65252	IEC lead	Ground floor	1	ok	0.14	>50	ok		13	Pass	
65253	Printer	Ground floor	1	ok	0.11	>50	ok			Pass	
65254	IEC lead	Ground floor	1	ok	0.07	>50	ok		13	Pass	
65255	IEC lead	Ground floor	1	ok	0.07	>50	ok		13	Pass	
65256	Water heater	Ground floor	1	ok	0.05	>50	ok			Pass	
65257	Fan	Ground floor	1	ok	0.08	>50	ok		3	Pass	

Failed Items Register

Premises: Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS						Technician: Ian Clifford					
Date: 14th May 2013						Tester: Primetest 200 X11-1203					
Asset Number	Description	Location	Class 1/2	Visual Check	Earth Bond (Ω)	Insulation ($M\Omega$)	Polarity	M/W Emmission	Fuse	Pass / Fail	Comments

65043	Fan	2nd floor	1	FAIL						FAIL	Cover damaged
-------	-----	-----------	---	------	--	--	--	--	--	------	---------------

REGISTER OF PORTABLE APPLIANCE TESTS

Client:

Example Report - Bpat Limited, Concorde House, Margaret Street, Brighton. BN2 1TS

Date(s) of Test:

14th May 2013

Testing of equipment has been carried out on the date(s) above according to the IEE Code of Practice for the in-Service Inspection & Testing of Electrical Equipment (4th edition - 2012)

RECOMMENDED DATE OF NEXT TEST: -

May 2015

Testing carried out by: -

BPAT Limited. Registered in England No. 7408430
Concorde House, Margaret Street, Brighton, East Sussex. BN2 1TS
T: 01273 457703 - info@bpat.co.uk
www.bpat.co.uk

Assets:	334
Assets Passed:	333
Assets Failed:	1

Cable repairs:	4
Plugs Replaced:	0
Fuses Replaced:	3

Equipment: Seaward PT 200 X11-1203

Calibrated: 15th July 2012

Calibration Cert. No. SEA35386R/1

Name: Ian Clifford

Position: Director

Signed:



ECA Member No. 110226

